



20126 Ballinger Way NE
#100
Shoreline, WA 98155

206.856.0757
425.640.0747

WORK ORDER #
13120

Date: 8-23-17

Billing: Kelly Damman
Address: 11602 2nd Ave NW

Email Sandra

Work Site:
Address: Same

City: Seattle State: WA Zip: 98107
Phone # 206-261-9364 PO#: Kelly

City: _____ State: _____ Zip: _____
Contact: Same

Notes:
Sewer inspection from 3" cleanout in closet behind main floor bathroom, 3" ABS to 4" cast iron pipe at 3ft at sft concrete pipe, city main at 10ft. no visible breaks or separations at this time, minor roots in first 30ft of line recommend Root X (foaming Root killer) annually

Operator: Josh
Equip. Used: Cam
of Feet: 101

Part: _____
Labor: 1 min
Subtotal: 245.00
Sales Tax: 5
Total: \$ 245.00

Payment Check# _____
CC: [Redacted]

Terms: Due on Receipt

Reel Rooter Services is a Limited Liability Company WA# REELRRS911JB

Reel Rooter Service LLC does not archive or keep copies of any technical reports or videos of services performed. If the findings are to be used in any real estate transactions it is recommended that you, the client, keep records for any future needs.

Our services include cleaning of sewer and drain lines, video scoping of sewer lines, and sewer line location of 2"-6" diameter pipe, as measured interiorly.

The warranty for cleaning services is 30 days from the date of service; this coverage does not include any misuse or negligence, including stoppage due to waste, paper and feminine hygiene products.

Video scoping provided by Reel Rooter Service LLC is unbiased and findings are based on what is seen by the technician on the day the service is performed. Any decisions or actions needed for engineering, repair or replacement of sewer or drain lines should be made by consulting a licensed sewer contractor that performs those services.

Location and depth of areas of interest of the pipe will be given. The equipment used can be affected by electrical or atmospheric disturbance; therefore, no guarantee is made of the exact location, depth or position. Excavation of such an area is done at the clients own risk and should only be done after consultation with an excavation expert.

Toilets may be lifted to provide access to a line, only upon the property owner's consent. Reel Rooter Service LLC shall not be liable for any damage to fixtures or flooring while providing this service. _____ (initial)

X Kelly Damman (authorized Signature)