



20126 Ballinger Way NE
#100
Shoreline, WA 98155

206.856.0757
425.640.0747

WORK ORDER #
14086

Date: 6-18-18

Billing: Sandra Brenner
Address: Sbrenner@windermere
City: _____ State: _____ Zip: _____
Phone # _____ PO#: Sandra

Work Site:
Address: 707 N 64th st
City: Seattle State: WA Zip: 98103
Contact: _____

Notes:
Sewer inspection 4" ABS cleanout in basement ABS pipe to ~~103ft~~
25ft cast iron from 2-5ft, to ABS line heads out back then wraps
around East side to city main on N 64th st, PVC at 57ft
4" x 6" transition at 103ft, city main at 145ft no visible breaks
or separations at this time,

Shared line with 711 & 715 N 64th at 103ft

Operator: Josh
Equip. Used: cam
of Feet: 145
Payment Check# _____
CC: _____

Part: _____
Labor: 1 min 260.00
Subtotal: _____
Sales Tax: 0
Total: \$ 260.00

Terms: Due on Receipt

Reel Rooter Services is a Limited Liability Company WA# REELRRS911JB

Reel Rooter Service LLC does not archive or keep copies of any technical reports or videos of services performed.
If the findings are to be used in any real estate transactions it is recommended that you, the client, keep records for any future needs.

Our services include cleaning of sewer and drain lines, video scoping of sewer lines, and sewer line location of 2"-6" diameter pipe, as measured interiorly.

The warranty for cleaning services is 30 days from the date of service; this coverage does not include any misuse or negligence, including stoppage due to waste, paper and feminine hygiene products.

Video scoping provided by Reel Rooter Service LLC is unbiased and findings are based on what is seen by the technician on the day the service is performed.
Any decisions or actions needed for engineering, repair or replacement of sewer or drain lines should be made by consulting a licensed sewer contractor that performs those services.

Location and depth of areas of interest of the pipe will be given. The equipment used can be affected by electrical or atmospheric disturbance; therefore, no guarantee is made of the exact location, depth or position. Excavation of such an area is done at the clients own risk and should only be done after consultation with an excavation expert.

Toilets may be lifted to provide access to a line, only upon the property owner's consent. Reel Rooter Service LLC shall not be liable for any damage to fixtures or flooring while providing this service. _____ (initial)

X _____ (authorized Signature)