

Continuous Radon Monitor

Model Number: 1028
Calibration Date: 08/15/2014
Monitor Time: 7/6/2015 16:45

Serial Number: 95034010
CF: 2.84

Inspection Company

Chris Hart
Great Divide Property Insp
P.O. Box 774902
Steamboat Springs, Co-80477
Phone Number: 970 819-2935

Billing Information

Benj Hoffner
29400 CR 14
Steamboat Springs, CO-80487

Site Information

Benj Hoffner
29400 CR 14
Steamboat Springs, CO-80487

Site & Condition


Wind: NA
Year Built: NA
Mitigation System: Not Installed
SqFt: NA

Atmospheric Condition: NA
Structure Type: NA
Monitor Location: NA

Test Summary

Start Time: 07/03/2015 10:31
End Time: 07/06/2015 12:31
Measurement Interval(hr): 2.0
Exposure Time: 3 Days 2 hrs

Overall Avg: 1.6 pCi/l
EPA Avg: 1.6 pCi/l



***** 07/03/2015 *****

Time	Counts pCi/l	Flags
12:31	0.9	
14:31	1.6	
16:31	0.7	
18:31	0.5	
20:31	0.2	
22:31	0.5	

***** 07/04/2015 *****

Time	Counts pCi/l	Flags
00:31	1.4	
02:31	1.1	
04:31	2.6	
06:31	2.8	
08:31	1.2	
10:31	2.3	
12:31	1.2	
14:31	1.2	
16:31	0.7	
18:31	0.0	
20:31	1.1	
22:31	0.7	

***** 07/05/2015 *****

Time	Counts pCi/l	Flags
00:31	1.4	
02:31	1.9	
04:31	1.9	
06:31	2.3	
08:31	3.5	
10:31	3.3	
12:31	2.6	
14:31	3.5	
16:31	1.8	
18:31	0.7	
20:31	1.6	
22:31	1.8	

***** 07/06/2015 *****

Time	Counts pCi/l	Flags
00:31	1.2	
02:31	1.4	
04:31	1.2	
06:31	1.8	


***** 07/06/2015 *****

Time	Counts pCi/l	Flags
08:31	1.4	
10:31	1.4	
12:31	1.9	

Error Flags:

M Motion:

Inspector Signature _____



PC Software Version: 2.2.0

Embedded Software Version: 109