For Informational Purposes Only

The field data upon which this map or plat is based has a closure precision of one foot in 10,000+ feet and an angular error of 02" per angle point, and was adjusted using COMPASS. This map or plat has been calculated for closure and is found to be accurate within one foot in 10,000+ feet. Legend: R.B.F. Rebar Found; R.B.P. Rebar Placed; M.H. Manhole; C.B. Catch Basin; H.W. Head Wall; D.I. Drop Inlet; J.B. Junction Box; R.W. Right of Way; B.L. Building Line; D.E. Drainage Easement; S.S.E. Sanitary Sewer Easement.



Survey for [illegible]

And ALVIN E. TREVILLIAN

Of property at 756 Brookline Trace

Lot 41, Block E, Park Brooke Subdivision Plat Book 141, Page 17

Land Lot [illegible]

Date 11/7/94 Scale 1" = 40'

THIS PROPERTY (IS) (IS NOT) LOCATED IN A FEDERAL FLOOD AREA AS INDICATED BY "FIA OFFICIAL FLOOD HAZARD MAPS"

BY ESTON PENDLEY & ASSOC., INC.

REGISTERED LAND SURVEYOR

GEORGIA REGISTERED No 945 PROFESSIONAL LAND SURVEYOR ESTON PENDLEY

In my opinion, this plat is a correct representation of the land platted and has been prepared in conformity with the minimum standards and requirements of law.

Eston Pendley

Member 5[illegible]